

TARDEC

---TECHNICAL REPORT---

THE NATION'S LABORATORY FOR ADVANCED AUTOMOTIVE TECHNOLOGY

No. 13766



WINNER OF THE 1995 PRESIDENTIAL AWARD FOR QUALITY

Laser Damage Testing of Molybdenum Shutter

May 1999

Thomas A. Whittaker
Robert V. Goedert
Andrew F. Clements
U.S. ARMY TAGOM, TARDEC
AMSTA-TR-R (MS 263)
By Warren, MI 48397-5000

Approved for Public Release: Distribution Is Unlimited

U.S. Army Tank-Automotive Research,
Development, and Engineering Center
Detroit Arsenal
Warren, Michigan 48397-5000

19990601 070

DTIC QUALITY INSPECTED 4

REPORT DOCUMENTATION PAGE

Form Approved
OMB No. 074-0188

Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing this collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302, and to the Office of Management and Budget, Paperwork Reduction Project (0704-0188), Washington, DC 20503

1. AGENCY USE ONLY (Leave blank)

2. REPORT DATE
May 1999

3. REPORT TYPE AND DATES COVERED
Technical Report

4. TITLE AND SUBTITLE

Laser Damage Testing of Molybdenum Shutter

5. FUNDING NUMBERS

6. AUTHOR(S)

Thomas A. Whittaker, Robert V. Goedert, and
Andrew F. Clements

7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES)

U.S. Army TACOM, TARDEC
AMSTA-TR-R (MS 263)
Warren, MI 48397-5000

8. PERFORMING ORGANIZATION
REPORT NUMBER

TARDEC Technical Report No. 13766

9. SPONSORING / MONITORING AGENCY NAME(S) AND ADDRESS(ES)

U.S. Army TACOM, TARDEC
AMSTA-TR-R (MS 263)
Warren, MI 48397-5000

10. SPONSORING / MONITORING
AGENCY REPORT NUMBER

TARDEC Technical Report No. 13766

11. SUPPLEMENTARY NOTES

12a. DISTRIBUTION / AVAILABILITY STATEMENT

Approved for Public Release: Distribution is unlimited

12b. DISTRIBUTION CODE

A

13. ABSTRACT (Maximum 200 Words)

This technical report presents the data collected from in-house laboratory testing of a Molybdenum shutter. Laser damage testing was performed on the sample using a Q-switched, frequency doubled Nd:YAG laser to determine the laser induced damage threshold of the material under typical operating conditions.

14. SUBJECT TERMS

Laser damage testing, Nd:YAG laser, Molybdenum, laser shutter

15. NUMBER OF PAGES

16. PRICE CODE

17. SECURITY CLASSIFICATION
OF REPORT

Unclassified

18. SECURITY CLASSIFICATION
OF THIS PAGE

Unclassified

19. SECURITY CLASSIFICATION
OF ABSTRACT

Unclassified

20. LIMITATION OF ABSTRACT

Unlimited

NSN 7540-01-280-5500

Standard Form 298 (Rev. 2-89)
Prescribed by ANSI Std. Z39-18
298-102

TABLE OF CONTENTS

1.0 SUMMARY.....	1
2.0 INTRODUCTION.....	1
3.0 LASER DAMAGE TESTING.....	1
3.1 Test Description.....	1
3.2 Test Equipment.....	1
3.3 Experimental Arrangement.....	2
3.4 Spot Size Determination.....	2
4.0 OBSERVATIONS/RESULTS.....	2
5.0 CONCLUSSIONS.....	5
6.0 RECOMMENDATIONS.....	5
DISTRIBUTION LIST.....	7

LIST OF ILLUSTRATIONS

<u>Figure</u>	<u>Page</u>
1. Experimental Arrangement.	2
2. Spot Size at Sample.....	2
3. Molybdenum Test Sample.....	3
4. Magnified Test Sites	3
5. Damage with Increasing Fluence	4
6. Comparison of Damage Spot Areas.....	4

1.0 SUMMARY

This technical report presents the data collected from in-house laboratory testing of a .004 " thick Molybdenum shutter. Laser damaging testing was performed on the sample using a Q-switched, frequency doubled Nd:YAG laser to determine the laser-induced damage threshold of the material under typical operating conditions. A total of eighteen sites were each exposed to 600 laser pulses. The laser was fired at a repetition rate of 10 Hz for a duration of 1 minute.

Test results show that the Molybdenum sample will damage when exposed to multiple laser pulses with fluences greater than or equal to 0.19 J/cm^2 . Results also showed that as the fluence increased the damaged area increased.

The authors recommend that this type of Molybdenum sample not be used as a shutter for TARDEC's Continuum Powerlite Nd:YAG laser because the sample will damage under typical operating conditions.

2.0 INTRODUCTION

The Emerging Technologies Team is searching for a fast, mechanical, external shutter for TARDEC's Continuum Powerlite Nd:YAG laser. A .004" thick Molybdenum sample was acquired from Vincent Associates as a potential shutter. A laser damage test was performed on the sample to determine if this material could function as a shutter for our application without damaging.

3.0 LASER DAMAGING TESTING

3.1 Test Description: Laser damaging testing was performed on the sample using a frequency doubled Nd:YAG laser to determine the laser-induced damage threshold of the material under typical operating conditions. The laser was operating in near TEM₀₀ mode with a 10-16ns pulse length. A total of eighteen sites were each exposed to 600 laser pulses. The laser was fired at a repetition rate of 10 Hz for a duration of 1 minute. Each site was exposed to a constant fluence level, but this fluence level was varied from site to site and ranged from 0.1 J/cm^2 to 1.8 J/cm^2 . The mirrored surface of the sample was exposed in a grid pattern with each site separated by 2.5 mm. After each site was exposed to the multiple shots, the sites were examined to determine if damage occurred. This examination was done with the naked eye and under a microscope.

3.2 Test Equipment:

- Continuum Q-switched Nd:YAG Laser
- Laser Probe Silicon Energy Detector, Model No. RJP-765 a
- Laser Probe Silicon Energy Detector, Model No. RJP-765 a
- Laser Probe RM-6600 Universal Radiometer

NIST Calibrated Neutral Density Filters

3.3 Experimental Arrangement: See Figure 1.




Figure 1. Experimental Arrangement

3.4 Spot Size Determination: The laser beam was focused onto the test sample with a plano-convex lens (40 mm diameter, $f=100$ mm). The $f/\#$ of this set-up was approximately 41. In order to determine the fluence level for each exposed site, it was necessary to




Figure 2. Spot Size at Sample

determine the spot size of the laser beam at the sample. This was accomplished by placing burn paper in the plane of the sample and recording a laser burn (see Figure 2). The burns were then examined under a microscope to determine their size. The spot diameter at the sample was determined to be $435\mu\text{m} \times 585\mu\text{m}$ or an average of $510\mu\text{m}$.

4.0 OBSERVATIONS/RESULTS

4.1 A summary of the laser damage test results for the Molybdenum shutter is presented in Table 1. Figure 3 shows the test sample after it had been tested. Figure 4 provides a close-up of the test sites showing a grid pattern. The circles in the figure show the sites that were not damaged. The scale shown at left of the figure is 1 millimeter/divison.

Site Number	Input Energy (mJ)	Fluence (J/cm ²)	Damage
1	3.22	1.57	Yes
2	0.26	0.13	No
3	0.85	0.42	Yes
4	1.76	0.86	Yes
5	3.47	1.70	Yes
6	2.43	1.19	Yes
7	2.44	1.19	Yes
8	1.83	0.90	Yes
9	0.95	0.47	Yes
10	0.39	0.19	Yes
11	0.38	0.19	Yes
12	3.38	1.66	Yes
13	3.69	1.81	Yes
14	0.28	0.14	No
15	3.46	1.69	Yes
16	0.27	0.13	No
17	3.47	1.70	Yes
18	0.20	0.10	No

Table 1. Summary of Test Results

4.2 The multiple shot laser-induced damage threshold for the Molybdenum test sample was 0.19 J/cm².




Figure 3. Molybdenum Test Sample




Figure 4. Magnified Test Sites

4.3 While testing the Molybdenum sample we noted that the damaged area increased as the fluence increased. This is illustrated in Figure 5. We also determined that the damage spot size increase is directly related to the increase in input fluence. For example: for site 15 the fluence was 1.69 J/cm² and the area of the damage spot was 159

mm² and for site 10 the fluence was 0.19 J/cm² and the area of the damage spot was 0.0177 mm² (see Figure 6). The ratio of the two site's fluences (8.90) and damage spot areas (8.98) was nearly identical.




Figure 5. Damage with Increasing Fluence

4.4 After examining the damage sites, it was apparent that several of the damage sites had a ring or halo surrounding the primary elliptical damage site. This effect was seen for input fluences greater than or equal to 1.19 J/cm². It was postulated that this ring was caused by a laser-induced shockwave. The ring may be the result of a shock propagating out from the center of the damage site, ejecting coating material at the peak of the first crest. The dark ring may be coating left intact at the first minimum.




Figure 6. Comparison of Damage Spot Areas

5.0 CONCLUSIONS

5.1 Laser damaging testing was performed on the sample using a frequency doubled Nd:YAG laser to determine the laser-induced damage threshold of the material under typical operating conditions.

5.2 Test results show that the Molybdenum sample will damage when exposed to fluences greater than or equal to 0.19 J/cm^2 . Results also showed that as the fluence increased the damaged area increased.

6.0 RECOMMENDATIONS

6.1 We recommend that this type of Molybdenum sample not be used as a shutter for TARDEC's Continuum Powerlite Nd:YAG laser because the sample will damage under typical operating conditions.

6.2 We recommend that other alternative materials be pursued for this application.

NOTICES

This report is not to be construed as an official Department of the Army position.

Destroy this report when it is no longer needed. Do not return it to the originator.

DISTRIBUTION LIST

	<u>Copies</u>
ATTN: DTIC OCA Defense Technical Information Center 8725 John J Kingman Rd STE 0944 Ft Belvoir, VA 22060-6218	1
Manager Defense Logistics Studies Information Exchange ATTN: AMXMC-D Fort Lee, VA 23801-6044	1
Commander U.S. Army TACOM ATTN: AMSTA-TR-O Warren, MI 48397-5000	1
Commander U.S. Army TACOM ATTN: AMSTA-TR-R (MS 263) Warren, MI 48397-5000	3
Vincent Associates 1255 University Ave. Rochester, NY 14607	1